

# KPA1500 OWNER'S MANUAL ERRATA

Rev B.2, July 7, 2022  
E740301

**MAKE THESE CORRECTIONS TO YOUR  
MANUAL OR ADD NOTES TO THE TEXT TO REFER  
TO THIS ERRATA AT THE PLACES INDICATED**

**Note: Newest corrections appear first.**

1. On page 13, "Positioning the KPA1500 RF Deck and Power Supply," the existing text says:  
Provide at least 4" (10 cm) clearance behind the RF Deck fans and above the Power Supply top cover.  
Allow at least 1" (2.5 cm) clearance around the top and sides of the RF Deck and around the sides of the Power Supply for normal cooling air flow.

It should say:

Provide at least 4" (10 cm) clearance above the RF Deck top cover, behind the fans and above the Power Supply top cover. Allow at least 1" (2.5 cm) clearance around the sides of the RF Deck and Power Supply for normal cooling air flow.

2. Page 11 Figure 1, item 4: TX Sample BNC connector. The coupler provides a -50 dBm signal.
3. Bottom of page 43, table footnote: "\*BCD band codes used by the KPA1500 are on page 49." The table is on page 50.
4. There is a typographical error on the Menu Items table, page 31. The Menu Entry "ATU XCVR KEY (Tech Mode Only)" mentions MCU version "5.93 and later." This should read "5.63 or later."