

KPA1500 OWNER'S MANUAL ERRATA

Rev B.1, April 3, 2021

1. There is a typographical error on the Menu Items table, page 31. The Menu Entry "*ATU XCVR KEY (Tech Mode Only)*" mentions MCU version "5.93 and later." This should read "5.63 or later."