

XV50, XV144, XV222 ASSEMBLY MANUAL ERRATA

Rev. E-2, October 11, 2018

BEFORE STARTING ASSEMBLY, MAKE THESE CHANGES TO YOUR ASSEMBLY MANUAL OR ANNOTE THE TEXT TO REFER TO THIS ERRATA AT THE PLACES INDICATED.

1. **Page 16, Parts List:** Change the color codes for L2 and L3 (E690028) to “silver-gold-red-red-silver”
2. **Page 39, Left Column, Fifth Step:** Change the color codes for L2 and L3 to “silver-gold-red-red-silver”
3. **Page 8, Parts List:** Change the part number E980067, to E980020